



Product Change Notification

CA-140 and CA-144 Cable Assembly

Description of Change: CA-140 and CA-144 changing raw cable due to extended lead time

Classification of Change: Supplier identification and ROS part number change

Reason for Change: Manage reasonable lead time to our customers. Supplier of raw cable (Falmat) experiencing extended lead time.

Expected Influence on Quality/Reliability/Performance: None. Cable material remains same - Polyurethane

Part Number/Series/Family Affected:

Current Part Number(s):	New Part Number(s):
CA-144-01-xx	CA-148-01-xx
CA-144-02-xx	CA-148-02-xx
CA-144-03-xx	CA-148-03-xx
CA-140-01-xx	CA-148-04-xx

Time Schedule:

Last Time Buy Date: All new orders will be supplied with new material

Last Time Shipment Date: Current backlog as of 9/28/2022 unaffected

Recommended Replacement: N/A

For further information please contact Remote Ocean System Sales:

TEL: 858-256-2810

Email: jamesc@rosys.com